

KDIP18-H2 - SPARE PARTS LIST

No.	Part Number	Description	Specifications	Stock No.	Qty.	Price	Remarks
1	12223000007007	Chassis subassembly			1	\$106.51	
2	12123000000801	Top volute			2	\$13.56	
3	12100103000584	Centrifuge fan			2	\$36.85	LX-154*158*12-41J
4	12123000000802	Bottom volute			2	\$20.16	
5	12222500000253	Fan motor axes clamp (left)			1	\$1.50	
6	12223000000537	Fan motor fixing board			1	\$5.10	
7	12222500000255	Fan motor axes clamp (right)			1	\$1.50	
8	11002015002521	Brushless DC Motor			1	\$270.39	ZKFN-160-8-1-2
9	15823000A03636	Evaporator Assembly			1	\$261.46	
9.1	11201007000136	Pipe Temperature Sensor			1	\$8.85	
9.2	15123000008692	Evaporator outlet pipe subassembly			1	\$53.24	
9.3	15500406000012	Copper nut			1	\$10.95	TLM-C03
9.4	15123000010347	Evaporator inlet pipe subassembly			1	\$76.70	
10	12223000006629	Evaporator right support board subassembly			1	\$8.55	
12	12823000000190	Water collector assembly			1	\$116.03	
13	17223000004456	Duct electronic control box subassembly			1	\$314.33	
13.1	12223000006630	Electronic control box			1	\$42.24	
13.3	17400401000075	Terminal			1	\$13.32	JXZ-PT5H-A
13.6	11201007000283	Room Temperature Sensor			1	\$6.30	
13.7	17123000003492	Duct main control board subassembly			1	\$208.88	
13.1	17400306000070	Reactor			1	\$71.00	R05094A
13.11	17122000030569	Inverter module subassembly			1	\$287.46	
14	12223000006627	Cover of electronic control box			1	\$15.00	
15	12223000A02735	Pipe clamp board subassembly			1	\$7.05	

This information is to be used by qualified HVAC technicians only and is subject to revision without notice

KDIP18-H2 - Parts Lis No. P5DP180102

Above prices are subject to S&H charges

DATE 18-02

KDIP18-H2 - SPARE PARTS LIST

No.	Part Number	Description	Specifications	Stock No.	Qty.	Price	Remarks
16	17223000000003	Duct display board subassembly			1	\$41.91	
16.1	17123000002712	Duct display board subassembly			1	\$36.08	
17	17317100001195	Wired controller			1	\$193.13	KJR-120C1/BTF-E(AU)
18	12223000006632	Rear cover subassembly			1	\$45.32	
19	12223000006636	Top cover subassembly			1	\$51.90	
34	11201005000006	Water Level Sensor			1	\$23.28	CGQ-SW-MS-4201-01
35	12623000000003	Pump pipe			1	\$26.04	
36	17400802000021	Motor subassembly			1	\$91.72	KFR-50Q/DY-A/ZT.DQ-2
37	12223000A02732	Exhaust pump subassembly			1	\$14.40	
38	12100510000021	Drain pipe			1	\$2.55	
39	12622500000004	Drain pump rubber washer			1	\$4.95	
40	12123000000043	Cover of water testing hole			1	\$0.75	
41	12622500000003	Drain pump rubber washer			1	\$0.60	
50	17317000A04396	Remote controller			1	\$53.00	RG57B/BGEU1
51	12117000002114	Bracket of remote Controller			1	\$4.50	
60	12223000008573	Rear beam subassembly			1	\$13.68	
62	12223000008576	Middle beam subassembly			1	\$80.50	
63	12223000008574	Left clapboard subassembly			1	\$50.05	
64	12223000008572	Right clapboard subassembly			1	\$28.27	
65	12223000008577	Right side plate			1	\$13.44	
66	12223000008578	Right clapboard subassembly			1	\$29.15	

This information is to be used by qualified HVAC technicians only and is subject to revision without notice

KDIP18-H2 - Parts Lis No. P5DP180102

Above prices are subject to S&H charges

DATE 18-02